

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

CoJCot

U.S. Patent No.: 7,051,798

Serial No.

: 10/785,409

Filed

: February 25, 2004

Issued

: May 30, 2006

For

: HEAT EXCHANGER

PETITION FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 C.F.R. § 1.322 OR § 1.323

Assistant Commissioner for Patents Washington, D. C. 20231

Sir:

Applicants hereby request that the above-identified U.S. patent be corrected in accordance with the attached Certificate of Correction.

I. C.F.R. § 1.322

The mistake(s) was incurred through the fault of the Patent and Trademark Office and is clearly disclosed in the records of the Office. Therefore, no fee is due.

II. C.F.R. § 1.323

At least some of the mistakes was made by the applicant. Therefore, a check in the amount of \$100.00 in payment of the fee set forth in 37 C.F.R. § 1.20(a) is enclosed herewith.

Enclosed herewith is a Form PTO-1050 (in duplicate) listing errors that have been found in the above-identified patent. The error(s) are of a clerical or typographical nature or of minor character and were made in good faith. The requested correction(s) do not constitute new matter or require reexamination.

DEC 1 1 2006

12/05/236 SZEUDIE1 03923389 7051798 01 F0:1011 109.03 00 III. Accordingly, patentees and their assignee respectfully request that the Patent and Trademark Office issue a Certificate of Correction pursuant to 37 C.F.R. § 1.322 or § 1.323, respectively.

Respectfully submitted,

Brion P. Heaney Keg. No. 32,542

Attorney for Applicants

MILLEN, WHITE, ZELANO & BRANIGAN, P.C.
Arlington Courthouse Plaza l
2200 Clarendon Blvd. Suite 1400
Arlington, Virginia 22201
Telephone: (703) 243-6333
Facsimile: (703) 243-6410

Attorney Docket No.: LINDE-0619

Date: December 5, 2006

BPH/rak

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 7,051,798

DATED: May 30, 2006

INVENTOR(S): Stefan MOELLER

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 6, line 24 reads "(6a, 5b; 7a, 7b)" should read -- (6a, 6b; 7a, 7b) -- Column 8, line 43 reads "arranged being arranged so as" should read -- arranged so as --

MAILING ADDRESS OF SENDER:

Millen, White, Zelano & Branigan, P.C. 2200 Clarendon Blvd, Suite 1400 Arlington, VA 22201

PATENT NO. 7,051,798

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.